



CERTIFICATION SCHEME FOR PERSONNEL

DOCUMENT No. CSWIP-ISO-NDT-11/93-R

Requirements for the Certification of Personnel Engaged in Non-Destructive Testing in accordance with the requirements of ISO 9712

APPENDIX 1

Examination and Syllabus Content details for CSWIP-ISO-NDT-11/93-R scheme

PART 4a Radiographic Interpreter Level 2

9th Edition, July 2026

Issued under the authority of the Governing Board for Certification
All correspondence should be addressed to:

TWI Certification Ltd
Granta Park, Great Abington, Cambridge CB21 6AL, UK
Telephone: +44 (0) 1223 899000
Email: personnel@twicertification.com
Website: www.cswip.com

CSWIP is administered by TWI Certification Ltd

1 EXAMINATION CONTENT

1.1.0 CSWIP Radiographic Interpreter Level 2: Welds

1.1.1 General theory examination

- 40 multiple-choice questions
- Time allowed: 80 minutes
- Pass mark: 70%

1.1.2 Specific theory examination

- 20 multiple-choice questions
- Time allowed: 60 minutes
- Pass mark: 70%

1.1.3 General practical examination

The candidate will be required to answer 16 multiple choice questions demonstrating an ability to understand and apply a given radiographic procedure followed by four questions on densitometry. This part of the examination will be based on a written procedure provided to the candidate (open book examination).

- Time allowed: 60 minutes
- Pass mark: 70%

1.1.4 Specific practical examination

Certification is awarded in a number of combinations of metal groups:

Group A: Ferritic steels including clad steels: manual metal arc, MIG, TIG and mechanised fusion welding, oxy-acetylene welding.

Group B: Austenitic steels and high nickel alloys (excluding Monel): manual metal arc, MIG, TIG and mechanised fusion welding. Titanium alloys: inert gas welding.

Group C: Aluminium and its alloys: MIG and TIG welding. Magnesium and its alloys: TIG welding.

Group D: Copper and its alloys and Monel: manual metal arc, MIG and TIG welding.

The candidate is required to read, mark up, interpret and report on six radiographs for Group A plus three radiographs for each additional group (B, C or D). A minimum of twelve radiographs must be submitted and passed by each candidate. For each radiograph the candidate is required to locate and identify defects and to comment upon radiographic technique and quality of the radiographs.

The duration of the second part depends on the number of metal groups attempted:

Candidates undertaking an online examination will be asked to complete seven multiple choice questions targeting key areas concerning each of the radiographs issued. Candidates will report on six radiographs for Group A plus three radiographs for each additional group, a minimum of 12 radiographs must be passed.

- Time allowed:
 - One group 1 hour 30 minutes
 - Two groups 2 hours 15 minutes
 - Three groups 3 hours
 - Four groups 3 hours 45 minutes
- Pass mark: 70%

1.1.5 Instruction writing examination

The candidate shall write an NDT instruction suitable for level 1 personnel as selected by the examiner.

- Time allowed: 60 minutes
- Pass mark: 70%

1.2.0 CSWIP Radiographic Interpreter Inspector Level 2: Castings

1.2.1 General theory examination

- 40 multiple-choice questions
- Time allowed: 80 minutes
- Pass mark: 70%

1.2.2 Specific theory examination

- 20 multiple-choice questions
- Time allowed: 60 minutes
- Pass mark: 70%

1.2.3 General practical examination

The candidate will be required to answer 16 multiple choice questions demonstrating an ability to understand and apply a given radiographic procedure followed by four questions on densitometry. This part of the examination will be based on a written procedure provided to the candidate (open book examination).

- Time allowed: 60 minutes
- Pass mark: 70%

1.2.4 Specific practical examination

The candidate is required to interpret 12 radiographs to gain certification. Candidates who wish to gain Dense metal or Light Alloy certification only will interpret and report on 12 Dense metal or 12 Light Alloy casting radiographs as selected by the examiner.

Candidates who wish to gain Dense metal and Light Alloy certification as a combined group will interpret and report on 12 radiographs from the two groups as selected by the examiner.

For each radiograph the candidate is required to locate and identify defects and to comment upon radiographic technique and quality of the radiographs. The duration of the second part depends on the number of metal groups attempted.

Candidates undertaking an online examination will be required to complete seven multiple choice questions for each radiograph issued targeting key areas.

- Time allowed: 4 hours
- Pass mark: 70%

1.2.5 Instruction writing examination

The candidate shall write an NDT instruction suitable for level 1 personnel as selected by the examiner.

- Time allowed: 60 minutes
- Pass mark: 70%

2 Ten Year Recertification

Candidates whose certificates expire at the end of the maximum ten year period of validity will be required to undertake a recertification examination comprising practical tests only as detailed below.

2.1 Radiographic interpreter (RI) (Welds)

The candidate is required to interpret two radiographs for the first group plus one radiograph each of any additional group. For each radiograph the candidate is required to locate and identify defects and to comment upon radiographic technique and quality of the radiographs.

Candidates undertaking an online examination will be required to complete seven multiple choice questions for each radiograph issued targeting key areas.

- Time allowed: 15 minutes per radiograph interpreted.
- Pass mark: 70%

2.2 Radiographic interpreter (R-Int) (castings)

The candidate is required to interpret two radiographs per group to gain certification.

For each radiograph the candidate is required to locate and identify defects and to comment upon radiographic technique and quality of the radiographs.

Candidates undertaking an online examination will be required to complete seven multiple choice questions for each radiograph issued targeting key areas.

- Time allowed: 15 minutes per radiograph interpreted.
- Pass mark: 70%

3 Examination Syllabus

3.1.0 Radiographic Interpreter (RI) (Welds) Level 2 Syllabus

3.1.1 General theory

a. Nature and Properties of X and/or Gamma Radiation

Penetration, absorption, scatter, diffraction, transmission. Rectilinear propagation. Photographic properties.

b. Photographic aspects

Dark room procedures: layout, light traps and entrance, wet and dry benches, film-pass hatches, processing units, safe-lights and ancillary equipment. Handling and processing of films, temperature control. Sensitometry: types of film and paper used in industrial radiography. Characteristic curves, speed, contrast, definition, density. Fog. Graininess. Inherent unsharpness. Latitude. Commercial films and their properties. The use of screens.

c. Fundamental aspects of Radiographic quality

Quality of radiation. Optimum working densities. Radiographic contrast. Objective and subjective contrast. Methods of controlling radiographic contrast. Effects of scattered radiation. Use of filters, screens, masking and blocking media. Influence of processing conditions and viewing conditions on contrast.

Radiographic definition: objective and subjective, unsharpness, geometric unsharpness, inter-relationship of dimensions of focal spot or source, focus (source) - object and focus (source) - film distances. Inherent unsharpness. Movement. Film screen contact. The summation of factors controlling definition.

Control of radiographic sensitivity and its assessment by the use of image quality indicators.

d. X-ray and Gamma ray equipment

A knowledge of the effects on radiographic quality in the event of equipment change.

e. Geometry of Image Formation

Control of focus (source) - object distance, object - film distance, focus (source) - film distance. Selection of beam angle.

3.1.2 Specific Theory - Welds

a. Exposure Calculations

Effect of distance on exposure. Use of exposure charts and calculators for X and gamma radiography.

b. Application to Welds

Interpretation of Radiographs in steel plate, and circumferential butt joints in steel pipe. Welds in aluminium. Welds in copper and its alloys. Welds in small bore tubes the determination of the depth of a flaw from one surface in a specimen by the practical use of the tube or source shift method.

c. Viewing of Radiographs

Optimum viewing conditions. Checking for acceptable density, contrast and freedom from spurious indications. Analyse the loss of sensitivity in order to rectify faulty techniques. Spurious indications: light (and safe-light) fogging, chemical fog, strains, air bubbles, reticulation, pressure marks, static marks, drying marks, finger marks, defective screens, incomplete fixing, film manufacturing faults.

d. Welding Technology

Terminology for welds, welded joints, welding procedures, weld defects, parent metal defects.

Influence on techniques of geometry, size, surface condition, parent metal composition, weld metal structure. Influence of surface cladding, heat treatments and weld repairs.

Basic principles of fusion welding processes. Types of defect associated with particular parent metal/welding process combinations.

Types of defect in welds and parent metals detectable by radiography. Defect parameters which influence detectability, eg size, geometry, distance from surface, orientation, reflectivity and opacity.

3.1.3 Specific theory – Castings

Casting Methods

Sand castings, pressure and gravity die casting, investment casting.

Casting Defects

Voids; porosity, gas and blowholes, airlocks and sponge

Surface defects; sinks, scabs, chisel and other fettling marks fins and flash.

Linear indications; hot tears, cold or stress cracks and cold shuts

Other defects; un-fused chill and chaplets, core shifts and mould damage.

Heat treatment

Common heat treatments and their reason for use.