



CERTIFICATION SCHEME FOR WELDING AND INSPECTION PERSONNEL

DOCUMENT NO. CSWIP-DIV-7-95 – Part 1, 2nd Edition September 2001

ERRATUM

Page 8: Para 4.3.3: Unsuccessful candidates

Delete from next heading ‘and Concrete examination’ – the heading should only read:

Initial 3.1U, 3.2U

as Concrete Examination carries no retest facility; the candidate must retake the full Initial examination.

As approved by the CSWIP In-Service Inspection Management Committee on 5 February 2003

Issued by TWI Certification Ltd
Granta Park
Great Abington
Cambridge CB1 6AL

Tel: +44 (0) 1223 891162
Fax +44 (0) 1223 894219
Email: twicertification@twi.co.uk
Web: <http://www.cswip.com>